

BACK

| | | | | | |
|---|---|--|--|--|--|
|  <p>M3-.5 HEX NUT</p>  <p>M30CNFH</p> |  <p>M3-.5 X 12 HEX CAP SCREW</p>  <p>M30C120HCS88Z</p> |  <p>M4-.7 HEX NUT</p>  <p>M40CNFH</p> |  <p>M4-.7 X 16 HEX CAP SCREW</p>  <p>M40C160HCS88Z</p> |  <p>M5-.8 HEX NUT</p>  <p>M50CNFH</p> |  <p>M5-.8 X 16 HEX CAP SCREW</p>  <p>M50C160HCS88Z</p> |
|  <p>M3 FLAT WASHER</p>  <p>M30NWF1Z</p> |  <p>M3-.5 X 16 HEX CAP SCREW</p>  <p>M30C160HCS88Z</p> |  <p>M4 FLAT WASHER</p>  <p>M40NWF1Z</p> |  <p>M4-.7 X 20 HEX CAP SCREW</p>  <p>M40C200HCS88Z</p> |  <p>M5 FLAT WASHER</p>  <p>M50NWF1Z</p> |  <p>M5-.8 X 20 HEX CAP SCREW</p>  <p>M50C200HCS88Z</p> |
|  <p>M3 INT STAR WASHER</p>  <p>M30NWIS</p> |  <p>M3-.5 X 20 HEX CAP SCREW</p>  <p>M30C200HCS88Z</p> |  <p>M4 INT STAR WASHER</p>  <p>M40NWIS</p> |  <p>M4-.7 X 25 HEX CAP SCREW</p>  <p>M40C250HCS88Z</p> |  <p>M5 INT STAR WASHER</p>  <p>M50NWIS</p> |  <p>M5-.8 X 25 HEX CAP SCREW</p>  <p>M50C250HCS88Z</p> |
|  <p>M3-.5 X 10 HEX CAP SCREW</p>  <p>M30C100HCS88Z</p> | |  <p>M4-.7 X 10 HEX CAP SCREW</p>  <p>M40C100HCS88Z</p> |  <p>M4-.7 X 30 HEX CAP SCREW</p>  <p>M40C300HCS88Z</p> |  <p>M5-.8 X 10 HEX CAP SCREW</p>  <p>M50C100HCS88Z</p> |  <p>M5-.8 X 30 HEX CAP SCREW</p>  <p>M50C300HCS88Z</p> |

FRONT