

BACK

IFACS-137

 <p>4 GA X 3/8 HOLE</p>  <p>BL-04-37-ST</p>			 <p>3/8-16 SS NUT</p>  <p>6015050</p>	 <p>1 & 2 GA POSITIVE</p>  <p>BT-01-P0-ST</p>	 <p>2/0 GA POSITIVE</p>  <p>BT-20-P0-ST</p>
 <p>4 GA X 5/16 HOLE</p>  <p>BL-04-31-ST</p>	 <p>1 & 2 GA X 1/2 HOLE</p>  <p>BL-01-50-ST</p>	 <p>1/0 GA X 1/2 HOLE</p>  <p>BL-10-50-ST</p>	 <p>2/0 GA X 1/2 HOLE</p>  <p>BL-20-50-ST</p>	 <p>1 & 2 GA NEGATIVE</p>  <p>BT-01-NE-ST</p>	 <p>2/0 GA NEGATIVE</p>  <p>BT-20-NE-ST</p>
 <p>4 GA X 1/4 HOLE</p>  <p>BL-04-25-ST</p>	 <p>1 & 2 GA X 3/8 HOLE</p>  <p>BL-01-37-ST</p>	 <p>1/0 GA X 3/8 HOLE</p>  <p>BL-10-37-ST</p>	 <p>2/0 GA X 3/8 HOLE</p>  <p>BL-20-37-ST</p>	 <p>4 GA POSITIVE</p>  <p>BT-04-P0-ST</p>	 <p>1/0 GA POSITIVE</p>  <p>BT-10-P0-ST</p>
 <p>4 GA SPLICE</p>  <p>BS-04</p>	 <p>1 & 2 GA SPLICE</p>  <p>BS-01</p>	 <p>1/0 GA SPLICE</p>  <p>BS-10</p>	 <p>2/0 GA SPLICE</p>  <p>BS-20</p>	 <p>4 GA NEGATIVE</p>  <p>BT-04-NE-ST</p>	 <p>1/0 GA NEGATIVE</p>  <p>BT-10-NE-ST</p>

FRONT